	- No.	, A 20.	A GEFFED W	IFREAGE	give recommended a recommendation of	A CONTROL OF THE STATE OF THE S
	Approved For	Release 2002/08/2	1: CIA-RDP89	9B00569R00	800120003-1	1201371013
	MATE 2147Z 16 APR	64	SECR	ET	S TO SECURE OF THE PROPERTY OF	The state of the s
		า ที่ ชนะคมสายคา ย กะ	in the standard Court of Burgerian of the street arounding	The management of the second second second second	A	All the many property of the many property of the many designation of the many designation of the many
	A PLANT TO A THE PROPERTY OF T	ahang meganggan digitarangan di disebigi sahidi yang sama (203, 11) (100 til 100 til 1, 200 melang meganggan digitarangan di disebigi sahidi yang sama (200, 200, 200, 200, 200, 200, 200, 200	et i varianninintarjanishiniya yardayariniya yazarini yazarini yazarini yazarini yaya Zirindirili 2000 - Osardi (2004) yazarini dalam i osafan sangiya energiya energiya	Miggard Frankricker (1921-1922) - Marchilla Margarith Latherson (1921-1921) 1- Caraller Santon, Marchill (1921-1922) - Barthall (1921-1924) - Albert (1921-1	15	Balling and the second of the second
	DIRECTOR					14
25X1	FFROM				The state of the s	135
20/(1	Predict		E	DD	ATTOCK ATTOCK OF THE UNIVERSAL PROPERTY OF THE OWNER, AND ADDRESS OF T	None of the second seco
	ACTION: OPS -	-8	R	S W	ROUTINE	·
	MFO :		1	B 14/5		Comments of the comments of th
		•	l.	IC 0		
	TOR 0055Z 17 AF	'R 64	1	SR	01	IN 73770
25X1			Į.	M	MSN 5084A	25X1
25X1	PRIORITY	(MEO	kan dina dina manganan kan sa kan dina dina dina dina dina dina dina di	COLUMN STATE OF THE STATE OF TH	CITE	***
25X1	*			÷	_	
	SUBJECT: FILM	EVALUATION M	ISSION SØ8	4À .		

- 1. CAMERA C 119 WAS USED IN MISSION SØ84A FLOWN ON 20 MARCH 1964; PROCESSING WAS ACCOMPLISHED BY
 - 2. ORIGINAL NEGATIVE:

25X1

Color Branch & For Sept 10

- A. THE EXPOSURE IS ADEQUATE. THE RESOLUTION IS FAIR TO GOOD.

 DEGRADATIONS ARE PRIMARILY DUE TO ATMOSPHERIC HAZE AND THE

 CHARACTERISTIC QUALITY DROP-OFF TOWARD ALL OUTBOARD CORNERS.
- B. 9R SIDE: THE FIRST 1840 FRAMES CONTAIN PRESSURE ROLLER STATIC (CHATTER) ALONG THE INBOARD EDGE OF THE FILM. SEVERAL, WAVERING PLUS DENSITY STREAKS OCCUR INTERMITTENTLY THROUGHOUT. PLUS DENSITY SPOTS ARE PRESENT 0.1" FROM THE OUTBOARD EDGE OF THE FILM FROM THE BEGINNING THROUGH FRAME 210. THE FIRST 385 FRAMES CONTAIN MINUS DENSITY DOTS, SPACED 2.32" APART, 3.55" FROM THE INBOARD EDGE OF THE FILM. A SHADOWGRAPH OF A WIRE IS PRESENT ADJACENT TO THE DATA CHAMBER ON EVERY FRAME. EMULSION DIGS OCCUR 1.6" FROM THE OUTBOARD EDGE OF FRAMES 359 THROUGH 2927. THE SPACING

SECRET

GROUP 1 Excluded from untercelle decorporation and declarification 25X1

BETWEEN THESE DIGS IS 6.4" BUT INCREASES SLIGHTLY TOWARD THE END
OF THE MISSION. A SIMILAR SERIES OF EMULSION DIGS OCCUR 4.92"
FROM THE OUTBOARD EDGE ON FRAMES 2071 THROUGH 2292. A TOTAL OF
FIVE TRANSVERSE STAINS, RESEMBLING WATER OR LACQUER, ARE NOTED
EDGE TO EDGE AND APPROXIMATELY 1.5" WIDE ON FRAMES 810, 811,
AND 812. THE FOLLOWING MINOR DEGRADATIONS WERE NOTED OCCASIONALLY
THROUGHOUT THE FILM, CLEANING SOLVENT SMEARED INTO THE FORMAT AREA,
TITLE AND LACQUER SMEARS, HANDLING MARKS, WATER MARKS, TEARS,
CHEMICAL STAINS, EMULSION RUBS, AND SCRATCHES. FRAMES 93 AND
2653 CONTAIN MANUFACTURER'S SPLICES.

9L SIDE: A FINE PLUS DENSITY STREAK IS PRESENT 4.23" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM HEAD TO TAIL. INTERMITTENT ABRASIONS OCCUR THROUGHOUT THE MISSION. PLUS DENSITY STREAKS. RANDOMLY LOCATED. ARE PRESENT INTER-MITTENTLY THROUGHOUT. TWO ROWS OF IRREGULARLY SPACED PLUS DENSITY SPOTS OCCUR 1.18" AND 2.08" FROM THE OUTBOARD EDGE OF THE FILM ON FRAMES 1338 THROUGH 1467. A ROW OF MINUS DENSITY DOTS. SPACED 2.32" APART, OCCURS Ø.87" FROM THE INBOARD EDGE ON FRAME 1694 AND GRADUALLY APPROACHES THE INBOARD EDGE. DIMINISHING AT THE EDGE ON FRAME 2645. DESENSITIZED SPOTS ARE PRESENT ON FRAMES 1417, 1418, AND 1687. INBOARD EDGE ROLLER CHATTER IS APPARENT ON APPROXIMATELY THE LAST 300 FRAMES OF THE MISSION. WATER SPOTS ARE NOTED ON FRAMES 1475-1478 AND 1467-1469. TAPE REPAIRED TEARS ARE PRESENT ON FRAMES 1864, 1865, 2316, AND 2317. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1689 WITH ASSOCIATED MINOR CREASES ON FRAMES 1689 THROUGH 1691 AND STATIC TRACES ON 1686, 1687, 1689, AND 1691.

Approved For Release 2002/08/21 : CIA-RDP89B00569R000800120003-1

(IN 73770) SECRET

PAGE THREE

- D. BOTH SIDES. INTERMITTENT DENDRITIC STATIC APPEARS
 THROUGHOUT THE MISSION CONCENTRATED ALONG THE INBOARD EDGE OF THE
 FILM. NUMEROUS SMALL PIECES OF FOREIGN MATTER ARE NOTED ADHERING
 TO BOTH SIDES OF THE FILM THROUGHOUT. PROCESSING STREAKS ARE
 PRESENT FROM HEAD TO TAIL. MANY FRAMES CONTAIN BLISTERS AND/OR
 PINHOLES. A BAND OF NUMEROUS SMALL EMULSION LIFTS IS PRESENT
 ALONG THE INBOARD EDGE OF THE FILM ON FRAMES 2316, 2317, AND 2318.
 HEAT SPLICES OCCUR BETWEEN FRAMES AT 266 FRAME INCREMENTS WITH
 A FEW EXCEPTIONS WHERE THE INCREMENT IS LESS. FRAMES ARE TITLED
 803 THROUGH 2927.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS DURING THIS MISSION.
 - 3. POSITIVES:
- A. PI SUITABILITY IS FAIR IN PART DUE TO DEGRADATIONS OF THE ORIGINAL NEGATIVES AND TO THE FAIR QUALITY OF THE DUPLICATE POSITIVES.
 - B. PRINTING AND PROCESSING IS FAIR.
 - C. CLOUDS OBSCURE APPROXIMATELY 40 PER CENT OF THE MISSION.
- D. SØ14A FLOWN 11 MARCH 1964 WAS ERRONEOUSLY INDICATED CAMERA NUMBER AS 199 AND SHOULD BE CAMERA 119.

END OF MESSAGE